





PARTS OF PROFILOMETER



1. MAIN BODY - 1 NO.
2. BEAM - 1 NO.
3. ARM - 2 NOS.
4. BRACKET (DIAL)- 1 NO.
5. BRACKET (REF. SCREW) - 1 NO.
6. REFERENCE SCREW - 1 NO.
7. WHEEL - 4 NOS
8. SPIRIT LEVEL -1 NO.
9. DIAL - 1 NO.